

Using the DigiTech meter



to measure & record
Temperature and Humidity

How to use the DigiTech meter?

To clear both memories

Press the left hand button and hold it down for more than 3 seconds .



The meter will then display the actual temperature and the relative humidity in the bottom and top panels respectively.

To display the MAXIMUM temperature

Press the left hand button once



To display the MINIMUM temperature

Press the left hand button a second time



To display THE ACTUAL temperature

Press the left hand button a third time

